


Power clamp cylinder——JCK Series


Compendium of JCK Series



Application








Specification

Model	JCK40	JCK50	JCK63	JCK80	
Output torque (0.5MPa)	120N.m	160N.m	380N.m	800N.m	
Acting type		Double	acting		
Fluid	Air(to b	e filtered by	40 μ m filter el	ement)	
Operating pressure		0.3~0.8MPa	a(43~116psi)		
Proof pressure	1.2MPa(175psi)				
Temperature		-10~	60 ℃		
Opening angle	15°/30	°/45°/60°/75°	/90°/105°/120	20°/135°	
Minimum opening and closure time	1 second clamping, 1 second opening				
Position sensing	Electrical or air Inductive approaching sensor				
Cushion type	Air buffer				
Weight (135°) [Note1]	2.2kg	4.0kg	5.5kg	13.0kg	
Port size [Note2]	1/8"		1/4"		

[Note1] This weight includes 15mm offset clamping arm;

[Note2] PT thread, G thread are available.




[Note1] Please refer to the right table for details of max. opening angle.

[Note2] Please refer to the drawing for detailed dimensions of clamping arm.

[Note3] K/KA type sensor switch can be ordered separately and please refer to relative contents.

KA type sensor switch cann't be ordered separately and 80 size no KA type.

Inner structure and material of major parts



NO.	Item	Material	
1	Adjusting screw	Free machining steel	
2	Back cover	Aluminum alloy	
3	Aluminum barrel	Aluminum alloy	
4	Front cover	Aluminum alloy	
5	Sensor switch		
6	Sensor switch fix	Plastic	
7	Y knuckle	Alloy steel	
8	Strengthen steel plate	Alloy steel	
9	Retaining pin	Carbon steel	
10	Connecting rod	Alloy steel	
11	Clamping arm	Cast steel	
12	Pivot	Alloy steel	
13	Piston rod	Carbon steel	
14	End cap	Aluminum alloy	
15	Piston	NBR	
16	Cushion body	Aluminum alloy	


Bore size	Arm position	Arm type	Maximum opening angle
	horizontal	AM1	135°
40	nonzontai	AM3	105°
40	Vertical()()	AM1	120°
	Vertical(V)	AM3	105°
50 63	horizontal	AM1、AM3 AM2、AM4	135°
80	Vertical(V)	AM1、AM3 AM2、AM4	105°



JCK Series——Standard type


How to select product


Please design appropriate fixture according to "Allowable Arm Load-Load Offset curve" diagram.





Bor	Maximum load torque				
size	1 second period	2 second period			
40	2.2Nm	3.3Nm			
50	4.5Nm	6.7Nm			
63	6.0Nm	9.0Nm			
80	8.0Nm	11.2Nm			

S: distance from pivot point to center of mass of clamping arm m: weight of clamping arm










Attention: Please use with speed control valve.


2. Please choose appropriate clamping position according to "Torque-Clamping Arm Length curve" diagram. Note: For clamping force is produced by elbow


mechanism, maximum torque is only reached at final clamping arm position.





Bore size	Maximum holder torque
40	380Nm
50	800Nm
63	1500Nm
80	2500Nm

Bore	Maximum clamp torque					
size	0.3MPa	0.4MPa	0.5MPa	0.6MPa	0.7MPa	0.8MPa
40	72Nm	95Nm	120Nm	143Nm	167Nm	191Nm
50	99Nm	132Nm	165Nm	198Nm	230Nm	264Nm
63	230Nm	307Nm	384Nm	460Nm	537Nm	614Nm
80	482Nm	643Nm	803Nm	964Nm	1124Nm	1285Nm









Please choose appropriate washer according to "Torque-Spacer thickness curve" diagram.

Note: Inserted washer exceeding maximum clamping torque position may lead to self-lock failure.


Take safety issue into account when considering thickness of spacer inserted.


Clamp arm length L(mm) A


Washer


Besides, clamping arm length L represents distance from pivot point to clamping position. For distance from mounting base locating hole to pivot A, please refer to the following table.

Bore size	A(mm)
40	12
50	10
63	10
80	15










Power clamp cylinder JCK Series——Standard type


Dimensions

JCK40AM1



With * dimension: pin hole position tolerance: ± 0.02 . Thread hole position tolerance: ± 0.1 .

JCK40AM3




With * dimension: pin hole position tolerance: ± 0.02 . Thread hole position tolerance: ± 0.1 .






JCK50AM1(2)




With * dimension: pin hole position tolerance: ± 0.02 . Thread hole position tolerance: ± 0.1 .


JCK50AM3(4)



Horizontal clamping position




Vertical clamping position




With * dimension: pin hole position tolerance: ±0.02. Thread hole position tolerance: ±0.1.




JCK63AM1(2)






With * dimension: pin hole position tolerance: ± 0.02 . Thread hole position tolerance: ± 0.1 .

JCK63AM3(4)






With * dimension: pin hole position tolerance: ±0.02. Thread hole position tolerance: ±0.1.




JCK80AM1(2)



With * dimension: pin hole position tolerance: ± 0.02 . Thread hole position tolerance: ± 0.1 .

JCK80AM3(4)



With * dimension: pin hole position tolerance: ±0.02. Thread hole position tolerance: ±0.1.



JCK Series——Air Inductive approaching sensor type




Specification

Model	JCK40□KA	JCK50□KA	JCK63□KA	
Output torque (0.5MPa)	120N.m	120N.m 160N.m		
Acting type		Double acting		
Fluid	Air(to be fil	tered by 40 μ m filt	er element)	
Operating pressure	0.3	~0.8MPa(43~116	psi)	
Proof pressure	1.2MPa(175psi)			
Temperature	-10~60 ℃			
Opening angle	15°/30°/45	°/60°/75°/90°/105	°/120°/135°	
Minimum opening and closure time	1 second	clamping, 1 secon	nd opening	
Position sensing	Air Indu	ıctive approaching	gsensor	
Cushion type	Air buffer			
Weight (135°) [Note1]	2.2kg	4.0kg	5.5kg	
Port size [Note2]	1/8" 1/4"			

[Note1] This weight includes 15mm offset clamping arm;


[Note2] PT thread, G thread are available.

Compendium of JCK(Air inductive approaching sensor type) Series



Installation and application

- 1. Can be mounted from three sides.
- 2. Air inductive approaching sensor is obturated completely which avoid dust and splashed welding slag breaking cylinders.
- 3. Adapt to air control loop's equipment. Main signal export to self-lock mechanism to check clamp or unclamp's position by air pressure signal.
- 4. Please connect air inductive approaching sensor's ports by the below sketch map.








JCK Series——Clamp arm and Adjusting screw




How to select clamp arm and adjusting screw

	Accessories\Cylinder type				JCK63	JCK80
	F-JCK□□X15LM	F-JCK□□X30LM	•	•	•	•
A alia tim a	F-JCK□□X45LM	F-JCK□□X60LM	•	•	•	•
Adjusting screw	F-JCK□□X75LM	F-JCK□□X90LM	•	•	•	•
sciew	F-JCK□□X105LM	F-JCK□□X120LM	•	•	•	•
	F-JCK□□X135LM		•	•	•	•
	F-JCK□□AM1R	F-JCK□□AM3R	•	•	•	•
	F-JCK□□AM1C	F-JCK□□AM3C	•	•	•	•
Clamp	F-JCK□□AM1L	F-JCK□□AM3L	•	•	•	•
arm	F-JCK□□AM2R	F-JCK□□AM4R		•	•	•
	F-JCK□□AM2C	F-JCK□□AM4C		•	•	•
	F-JCK□□AM2L	F-JCK□□AM4L		•	•	•

Adjusting screw ordering code



Clamp arm ordering code







Power clamp cylinder JCK Series——Clamp arm and Adjusting screw


Dimensions of clamp arm

F-JCK40AM1







F-JCK40AM3




F-JCK50AM1




F-JCK50AM2



F-JCK50AM3





F-JCK50AM4□








JCK Series——Clamp arm and Adjusting screw

















JCK Series——Sensor switch




-


Specification


Operating range	2mm
Voltage range	10~30V DC
Output type	N.O., PNP, NPN
Rated DC	150mA(max)
Switch frequency	30Hz
Shell material	PBT
Switch status	Clamping: Red
indication	Opering: Yellow
Voltage indication	Green


Ordering code




Hookup











Installation and application of sensor switch

- 1. Sensor switch is well assembled before leaving factory which is free of adjusting. If you need to change terminals' wiring direction, change new sensor or rearrange angle, please do as follows:
- 1.1) Steps of changing terminals' wiring direction:



(See figure above.) Unscrew the hexagon bolt→dismount sensor's Terminal→change terminals' wiring direction as you need→remounting→screw up the hexagon bolt.

1.2) Steps of change new sensor switch:



(See figure above.) unscrew two hexagon bolts ①→dismount sensor seats as a whole→unscrew two hexagon bolts ③→dismount two sensor switch contacts(SO1\SO2)→unscrew hexagon bolt ②→remove the sensor switch→choose new sensor switch →replace new sensor switch contact and screw up hexagon bolt ②→replace new wiring box and screw up hexagon bolt ①→finished.

Ecommended lock torque of hexagon bolt is listed in the following table:

	Ecommended lock torque of hexagon bolt ① Ecommended lock torque of hexagon bolt ② Ecommended lock torque of hexa					
Bore size	Hexagon bolt type	Lock torque(N.m)	Hexagon bolt type	Lock torque(N.m)	Hexagon bolt type	Lock torque(N.m)
40、50	M3×0.5	1.2~1.5	M5 × 0.8	4.0~5.0	M3 × 0.5	1.2~1.5
63、80	M5×0.8	4.0~5.0	IVI3 × U.6	4.0~5.0	0.0 × 6101	1.2~1.5

- 1.3) Steps of readjusting angle: For more details, see latter contents.
- 1.4) Sensor switch's connection:

Sensor switch's connection need to use relevant male connector, which have separate male connector, and with wire male connector to be choused. The ordering code as below:

The ordering dode as below.			
Name: On end cable(3 meters length)	Name: L shape cable(3 meters length)	Name: On end connector(rotundity)	Name: L shape connector (rotundity)
Ordering code: X-F-PPVCS	Ordering code: X-F-PPVCL	Ordering code: X-F-PPVCV	Ordering code: X-F-PPVCH
6300	No. of the last of		




Power clamp cylinder

JCK Series


Installation and application

- 1. Mount the cylinder at desired place with bolts and locating pin after choosing a mounting surface. Connect the cylinder and control valve with joint and rubber hose. To adjust the opening and closure speed, our pneumatic power welding clamp is equipped with return stroke air buffering. Buffering cannot function well if the clamping arm is over-weighted so that clamping arm' weight must be within the allowable limit;
- 2. Using clamping arm beyond the listed in this catalog is forbidden.
- 3. Workpiece mounting method:
 - 3.1) When only clamping torque is used for clamping:



Please follow the steps to mount the workpiece onto the clamping arm:

- A) Clamping the arm: supply compressed air through the inlet on the clamping side to keep the arm and pressing block at the closure position simultaneously. Make sure the arm is locked up.
- **B)** Adjusting the clamping gap: adjust the spacer under the mentioned state to make the pressing block in line with the workpiece's thickness. (At this moment no clamping torque is produced theoretically.)
- C) Applying clamping torque: Insert the spacer furthermore under the mentioned state until the gap is smaller than the workpiece's thickness and desired clamping torque is produced. (Make sure the mechanism passes the dead position to produce self-locking i.e. the retaining pin is pushed out.)
- 3.2) When hard braking is used for clamping:



Please follow the steps to mount the workpiece onto the clamping arm:

 A) clamping the arm: supply compressed air through the inlet on the closure side to keep the arm and the braking block at the clamping position simultaneously. Make sure the arm is locked up;

- B) Adjusting the clamping gap: Adjust washer ① under the mentioned state until the gap between the upside braking block and downside one. (At this moment no clamping torque is produced theoretically.)
- C) Applying clamping torque: insert the washer 1 furthermore under the mentioned state to produce desired clamping torque. (Make sure the mechanism passes the dead position to produce self-locking i.e. the retaining pin is pushed out.)
- D) Adjust washer ② under the state mentioned in C to make the pressing block in contact with the workpiece.

Side guide plate Clamping arm


3.3) When side guide plate is mounted:
Side guide plate is mounted on the clamping arm to prevent transverse movement and make sure that no transverse load is applied and that the arm would not be stuck.



4. Angle adjusting method::

Standard adjusting angle range of the pneumatic clamp is 15° ~135°. Opening angle can be changed via changing cylinder's stroke distance or the sensor's position;

4.1) Step 1 of adjusting angle--change of sensor's position:



- A) Unscrew hexagon bolt ① with inner hexagon wrench to take out the sensor seats:
- B) Unscrew hexagon bolt ③ with inner hexagon wrench to take out sensor SO1 and align it to your desired angle indication positon and re-screw up hexagon bolt ③. (Note: when mounting sensor SO1, the number "SO1" should point downward except 15°.)
- C) After the sensor's position is adjusted, replace the sensor seats by screwing up hexagon bolt ① with inner hexagon wrench (lock-up torque by related contents).

Note: 1) sensor SO2 controls the cylinder's end stroke position and its mounting position is well set when leaving factory and is not changeable.

Sensor Switch

Y Knuck

- 2) the sensor wiring box is (SO2) provided with two outgoing orientations: forward and downward. Unscrew hexagon bolt 2 and then you can change the wiring box orientation. After that, screw up hexagon bolt 2.
- When remounting the sensor fix to its original position, the gap between the sensor and Y-knuckle should be less than 1.5mm. Otherwise, the sensor may not function well.
- 4.2) Step 2 of adjusting angle--change of the cylinder's stroke distance:
 The relation between the opening angle of clamping arm and
 cylinder's stroke distance is listed as follows:

Opening angle\Type	JCK40	JCK50	JCK63	JCK80
15°	20.2	21.6	23.1	36.1
30°	28.1	30.2	33.4	50.5
45°	34.8	37.5	41.6	62.7
60°	41.4	44.6	49.7	74.5
75°	48.0	51.8	57.5	86.3
90°	54.8	59.2	65.7	98.1
105°	61.5	66.4	73.8	109.6
120°	67.4	72.7	81.0	119.5
135°	71.6	77.3	86.2	126.4



AITAL

JCK Series

During actual operation, the cylinder's stroke can be changed by changing the adjusting screw at the bottom to control the clamping arm's opening angle. Detailed description is

as follows:

Cylinder

Adjusting screw


- A) Unscrew original adjusting screw with inner hexagon wrench
- B) Choose suitable adjusting screw according to actual need (the bottom is marked with corresponding opening angle).
- C) Screw up new adjusting screw into the cylinder's end cap.
- 5. Mounting clamping arm:

The clamping arm is already mounted when leaving factory which can be remounted by yourself horizontally or vertically according to your actual need.

5.1) Mounting clamping arm horizontally:

Unscrew 4 hexagon bolts on both sides of the clamping arm to remove V-shaped block and then the clamping arm for substituting your desired one.


When mounting, please note the direction of the indicating line on the




Indicating line on the pivot does not point to the clamping arm and V-shaped block mounting surface.

5.2) Mounting clamping arm vertically:

Indicating line on the pivot point to the clamping arm and V-shaped block mounting surface.



5.3) V-shaped block mounting:



5.4) Holding torque of clamping arm (recommended):

When holding clamping arm, please choose recommended value in the following list:

Bore size	Bolt type	Holding torque (N.m)
40	M6×1.0	13.8
50	M6×1.0	13.8
63	M8×1.25	33.0
80	M10×1.5	66.0

6. Self-lock function:


At the end of stroke, the crank-slider mechanism passes the dead point and gets self-locked up. The retaining pin gets pushed up at this moment. Even when compressed air is off, the cylinder can remain at closure state for safety. To open self-locking of the crank-slider mechanism, push down the retaining pin when compressed air is off.

Warning:

Pushing down the retaining pin may cause clamping arm to spring off at closure state.

So when ushing the pin, please get yourself away from the clamping arm's operation range.

Pushing down the retaining



Retaining pin not pushed up, crank-slider mechanism not self-locked

Retaining pin pushed up, crank-slider mechanism self-locked